## Mitch Terpening DPW Report FEB. 8, 2017

1) Called on tables. Unable to get them through the Fairgrounds.

2) Need a sign for village office, to hang on the building.

3) Training seminar Completed.

4) 214 Higgins water service broke. New curb stop had to be replaced.

5) Installed new door.

- 6) Cummunity hall thermastate set 50 degrees. Curb stop shut off isn't working.
- 7) Have used approximently 50% of salt.
- 8) Plow and remove snow.