

**Mitch Terpening**  
**DPW Report**  
**April 10, 2019**

- 1) Met with ISO. Did flow test on some hydrants
- 2) Worked on pot holes on Grandriver Rd
- 3) Worked on alleys
- 4) Worked on Valve leak at treatment plant
- 5) Took unused salt back to the county for a credit
- 6) Cleaned out the dumptruck, greased and storing it in treatment plant
- 7) Cleaned up area around the water main break on Grandriver Rd
- 8)