

Mitch Terpening
DPW Report
Jan 16, 2020

- 1) Did yearly well inspection with Northern Well and Pump
- 2) Fixed Generator for well
- 3) Changed chlorine pump and cleaned chlorine injector
- 4) Did DEQ reports
 - : Lead and copper sampline plan
 - : Preliminary distribution system materials inventory
 - : Monthly bacterial report
- 5) Removed decals from green truck and prepared to sell
- 6) Salted and plowed roads
- 7) Installed new cutting edge on the backhoe